




DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE CUTTING / STITCHING. FABRIC SHOULD BE SOAKED BE SOAKED IN WATER
[ALL COMPONENTS SEPARATELY] FOR 15 MINUTES
DO NOT KEEP WET FABRIC IN TWISTED FROM IN ORDER TO AVOID COPY MRKS!
WASH COLOURED AND WHITE FABRICS SEPARATELY

IDON CLOTUCE OF MODEDOTE TEMPEDOTIDE LOO NOT DOV CODDIC IN DIDECT CHINICUT





DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE CUTTING / STITCHING. FABRIC SHOULD BE SOAKED BE SOAKED IN WATER
[ALL COMPONENTS SEPARATELY] FOR 15 MINUTES
DO NOT KEEP WET FABRIC IN TWISTED FROM IN ORDER TO AVOID COPY MRKS!
WASH COLOURED AND WHITE FABRICS SEPARATELY

IDON CLOTUCE OF MODEDOTE TEMPEDOTIDE LOO NOT DOV CORDIC IN DIRECT CHINICUT





DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE CUTTING / STITCHING. FABRIC SHOULD BE SOAKED BE SOAKED IN WATER
[ALL COMPONENTS SEPARATELY] FOR 15 MINUTES
DO NOT KEEP WET FABRIC IN TWISTED FROM IN ORDER TO AVOID COPY MRKS!
WASH COLOURED AND WHITE FABRICS SEPARATELY

IDON CLOTUCE OF MODEDOTE TEMPEDOTIDE LOO NOT DOV CODDIC IN DIRECT CHINICUT





DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE CUTTING / STITCHING. FABRIC SHOULD BE SOAKED BE SOAKED IN WATER
[ALL COMPONENTS SEPARATELY] FOR 15 MINUTES
DO NOT KEEP WET FABRIC IN TWISTED FROM IN ORDER TO AVOID COPY MRKS!
WASH COLOURED AND WHITE FABRICS SEPARATELY

IDON CLOTUCE OF MODEDOTE TEMPEDOTIDE I DO NOT DOV CORDIC IN DIRECT CUNICUT